


HAZARDOUS WASTE SITES
EVALUATION OF SECTION 311 CLEANUP REQUIREMENTS
ENVIRONMENTAL EMERGENCY SECTION
EPA - REGION X

1.1.2

SITE IDENTIFICATION			
Site Name: Resource Recovery		Street: Highway 12	
City: Pasco	State: WA	Zip: 99301	County:
PRINCIPAL EVALUATOR			
Name: R. Fullner		Title: TATL	
Organization: E/E		Telephone Number: 624-9537	
METHOD OF EVALUATION			
On-Site Inspection <input type="checkbox"/>		Review of reports and information <input checked="" type="checkbox"/>	
Date:		Date: 2-21-80	
EVALUATION INFORMATION			
1. a. Is there evidence of a discharge/seepage from the site?		Yes	No
b. Indicate the nature of the evidence:		Unknown X	
<input type="checkbox"/> Visible flow/seepage. <input type="checkbox"/> Odors detectable in soil/water outside of site boundaries. <input type="checkbox"/> Stains/discoloration of soil/water around site. <input type="checkbox"/> Sample analysis. <input type="checkbox"/> Other:			
2. a. Is there a substantial threat of discharge/seepage from the site?		Yes	No
b. Indicate the nature of the evidence:		Unknown X	
<input type="checkbox"/> Dikes or other containment structures are inadequate/lacking. <input type="checkbox"/> Waste materials are visible on the site surface. <input type="checkbox"/> High groundwater table. <input type="checkbox"/> Leaking containers, standing liquids, are visible. <input type="checkbox"/> Inadequate site security. <input type="checkbox"/> Other:			
<div style="text-align: right;"> USEPA SF  1426460 </div>			
Note: If you answered no to both question 1 and 2, proceed to question 7.			

3. a. Is there evidence that the actual or potential discharge/seepage is entering or could enter navigable waters of the United States?	Yes	No	Unknown X
b. Indicate the nature of the evidence: <input type="checkbox"/> Discharge/seepage observed entering a navigable water. Name of water body: _____ <input type="checkbox"/> Land contour and drainage patterns indicate that, during rainstorms, material could be expected to enter navigable waters. Name of water body: _____ <input type="checkbox"/> Other: _____			
4. a. Is the material in item 3 above a designated hazardous material according to 40CFR116?	Yes	No	Unknown
b. How was this determined? <input type="checkbox"/> Sample analysis. <input type="checkbox"/> From available information concerning materials handled or disposed of at the site. <input type="checkbox"/> Other: _____			
5. Has the owner/operator of the facility been identified?	Yes X	No	Unknown
6. Will the owner/operator take proper action to eliminate the actual or potential discharge?	Yes	No	Unknown
7. In your opinion, is this site eligible for cleanup under section 311?	Yes	No	Potential X
8. Comments: <div style="text-align: center; font-style: italic;">Insufficient information available.</div>			
Attachments: <div style="display: flex; justify-content: space-between;"> _____ Photo(s) _____ Map(s) _____ Analytical Results _____ Other: </div>			